


CUSTOM COOLER, INC



NOTE:

FOR ALL MECHANICALLY FASTENED ANCHORS,  
SPECIAL INSPECTION MAY BE REQUIRED,  
VERIFY WITH LOCAL BUILDING OFFICIAL.

CUSTOM COOLER CLP 600 SERIES  
FREEZER WALL PANEL CONNECTION TO SLAB  
WITH THERMAL BREAK